

CAPISTRANO BAY DISTRICT
AGENDA REPORT
February 26, 2013

Managers Reports

ITEM J.2

Additonal Surveillance Camera at the Guard Building

The District currently has five cameras around the guard shack capturing images of activity in and out of the community. There is, however, a blind area within the residents' entry driveway immediately adjacent to the guard building. This became apparent back in December when a vehicle may have brushed a pedestrian in the driveway and there were no images captured on any of the existing cameras to show what transpired.

The previous five cameras have been installed by Maximum Security Alarm Systems. This vendor was selected from a group of bidders last year as having the most reasonably priced bid. The proposal for this additional camera is unit-priced the same as the other cameras they installed at \$633.24.

There is a need for this additional camera to complete a full unbroken circle of coverage around the guard building.